

135	盤、 ルー タ、木 エフラ イス盤							1												1
136	チェー ンソー				2			18												20
139	その他 の木材 加工用 機械				1			4												5
141	整地・ 運搬・ 積込み 用機械	12	9	1	1	1	17	33	1							1				76
142	掘削用 機械	35	14	5	17	2	83	89										1		246
143	基礎工 事用機 械	1		1		1		5												8
144	締固め 用機械	12	5	3	3	1	23	42	1									1		91
145	解体用 機械		2		9		3	4										1	1	20
146	高所作 業車						1													1
149	その他 の建設	8	3	3	12	1	20	22	8			2	2			2		1	1	85

	合掌																				
416	作業 床、歩 み板	14	16	5			1												3		39
417	通路	17	73	10	1						1								3		105
418	建築 物、構 築物	49	18	9	5	11		2											1		95
419	その他 の仮設 物、建 築物、 構築物 等	14	8	5	5	5	2	4	1										4		48
511	爆発性 の物等																				
512	引火性 の物										1										1
513	可燃性 のガス										1			1							2
514	有害物											1									1
515	放射線																				
519	その他 の危険 物、有 害物等				1						1	3	3								8
521	金属材 料	2	4	4	38	11	6	20		3									4	1	93

921	なし		3				1													22	2		28
999	分類不能	1					1																2
	計	536	249	101	327	92	269	435	133	3	1	41	7	3	3	5	3	152	3	94	12		2,469

事例数に2011年の東日本大震災の災害事例は含まれていない。死傷災害全数の約1/4の抽出事例数である。

出典：https://anzeninfo.mhlw.go.jp/anzen_pgm/SHISYO_FND.aspx(職場のあんぜんサイト)

Return to https://www.jisha.or.jp/international/topics/202207_04.html