

415	crossbeam, principal rafter																								0
416	working platform, boot board																								0
417	passage																								0
418	building, establishment	1					1									1									3
419	other temporary buildings, establishments																								0
511	explosive substance																								0
512	inflammable substance															1									1
513	inflammable gas																								0
514	harmful substance																								0
515	radiation																								0
519	other hazards, harmful substances																								0
521	metal material																								0
522	lumber, bamboo																								0
523	stone, sand, substance																								0
529	other materials																								0
611	load					1	1																		2
612	machine/equipment as load																								0
711	natural ground, rock	1																							1
712	standing tree																								0
713	water																								0
714	abnormal environment																								0
715	high/cold temperature environment										1														1
719	other environments						3																		3
911	other causal agent																								0
921	no causal agent																				3				3
999	unclassifiable																								0
000	total	7	2	1	1	2	6	14	4	0	0	2	0	1	1	0	2	12	0	0	3	0		58	

Data of 2011 year do not include Industrial accidents caused by Great East Japan Earthquake in 2011.

Data sources: https://anzeninfo.mhlw.go.jp/anzen_pg/SIB_FND.aspx (MHLW, Japan)

Return to <https://www.jisha.or.jp/english/statistics/2020efretcs.html>

