

415	crossbeam, principal rafter																						0
416	working platform, boot board	1																					1
417	passage																						0
418	building, establishment	3																					3
419	other temporary buildings, establishments									1													1
511	explosive substance																						0
512	inflammable substance																						0
513	inflammable gas																						0
514	harmful substance																						0
515	radiation																						0
519	other hazards, harmful substances																						0
521	metal material																						0
522	lumber, bamboo																						0
523	stone, sand, substance																						0
529	other materials																						0
611	load																						0
612	machine/equipment as load																						0
711	natural ground, rock																						0
712	standing tree																						0
713	water																						0
714	abnormal environment												1										1
715	high/cold temperature environment																						0
719	other environments																						0
911	other causal agent									1													1
921	no causal agent																				1		1
999	unclassifiable																					1	1
000	total	13	0	0	0	0	2	2	0	0	5	1	1	0	1	1	0	4	0	0	1	1	32

Data of 2011 year do not include Industrial accidents caused by Great East Japan Earthquake in 2011.

Data sources: https://anzeninfo.mhlw.go.jp/anzen_pg/SIB_FND.aspx (MHLW, Japan)

Return to <https://www.jisha.or.jp/english/statistics/2020efretcs.html>

