

415	crossbeam, principal rafter																																								0
416	working platform, boot board																																								0
417	passage																																								0
418	building, establishment																																								0
419	other temporary buildings, establishments																																								0
511	explosive substance																																								0
512	inflammable substance																																								0
513	inflammable gas																																								0
514	harmful substance																																								0
515	radiation																																								0
519	other hazards, harmful substances																																								0
521	metal material																																								0
522	lumber, bamboo																																								0
523	stone, sand, substance																																								0
529	other materials																																								0
611	load																																								0
612	machine/equipment as load																																								0
711	natural ground, rock																																								0
712	standing tree																																								0
713	water																																								0
714	abnormal environment																																								0
715	high/cold temperature environment																																								0
719	other environments																																								0
911	other causal agent																																								0
921	no causal agent																																								0
999	unclassifiable																																								0
000	total	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	3		

Data of 2011 year do not include Industrial accidents caused by Great East Japan Earthquake in 2011.

Data sources: https://anzeninfo.mhlw.go.jp/anzen_pg/SIB_FND.aspx (MHLW, Japan)

Return to <https://www.jisha.or.jp/english/statistics/2020efretcs.html>

