

415	crossbeam, principal rafter	1								1													2
416	working platform, boot board	2																					2
417	passage									1													1
418	building, establishment							1															1
419	other temporary buildings, establishments																						0
511	explosive substance																						0
512	inflammable substance													2		1							3
513	inflammable gas																						0
514	harmful substance												1										1
515	radiation																						0
519	other hazards, harmful substances														1								1
521	metal material				1																		1
522	lumber, bamboo																						0
523	stone, sand, substance																						0
529	other materials				1																		1
611	load																						0
612	machine/equipment as load																						0
711	natural ground, rock																						0
712	standing tree																						0
713	water									1													1
714	abnormal environment																						0
715	high/cold temperature environment										1												1
719	other environments																						0
911	other causal agent																						0
921	no causal agent																						0
999	unclassifiable																						0
000	total	10	0	0	4	0	0	16	0	1	2	1	1	0	3	0	1	0	0	0	0	0	39

Data of 2011 year do not include Industrial accidents caused by Great East Japan Earthquake in 2011.

Data sources: https://anzeninfo.mhlw.go.jp/anzen_pg/SIB_FND.aspx (MHLW, Japan)

Return to <https://www.jisha.or.jp/english/statistics/2020efretcs.html>

