







415	crossbeam, principal rafter	1																					1
416	working platform, boot board																						0
417	passage	1																					1
418	building, establishment	2																					2
419	other temporary buildings, establishments																						0
511	explosive substance						1							5									6
512	inflammable substance													2		1							3
513	inflammable gas																						0
514	harmful substance											8											8
515	radiation																						0
519	other hazards, harmful substances													3		2							5
521	metal material																						0
522	lumber, bamboo																						0
523	stone, sand, substance																						0
529	other materials																						0
611	load																						0
612	machine/equipment as load																						0
711	natural ground, rock																						0
712	standing tree																						0
713	water																						0
714	abnormal environment											1											1
715	high/cold temperature environment																						0
719	other environments																						0
911	other causal agent													2									2
921	no causal agent																						0
999	unclassifiable																				1		1
000	total	9	1	1	0	0	4	16	0	0	0	1	9	0	12	1	3	4	0	0	0	1	62

Data of 2011 year do not include Industrial accidents caused by Great East Japan Earthquake in 2011.

Data sources: [https://anzeninfo.mhlw.go.jp/anzen\\_pg/SIB\\_FND.aspx](https://anzeninfo.mhlw.go.jp/anzen_pg/SIB_FND.aspx) (MHLW, Japan)

Return to <https://www.jisha.or.jp/english/statistics/2020efretcs.html>

