

415	crossbeam, principal rafter	2																					2
416	working platform, boot board	3																					3
417	passage		1																				1
418	building, establishment	20			1	4					3												28
419	other temporary buildings, establishments				1	3																	4
511	explosive substance																						0
512	inflammable substance																						0
513	inflammable gas																						0
514	harmful substance																						0
515	radiation																						0
519	other hazards, harmful substances																						0
521	metal material			1		1		2															4
522	lumber, bamboo																						0
523	stone, sand, substance	3				10																	13
529	other materials				2	3		1															6
611	load	1			1	7	2	1															12
612	machine/equipment as load																						0
711	natural ground, rock	1				2																	3
712	standing tree																						0
713	water									3													3
714	abnormal environment																						0
715	high/cold temperature environment										3										1		4
719	other environments																						0
911	other causal agent																				2		2
921	no causal agent																				1		1
999	unclassifiable																						0
000	total	61	6	1	13	40	17	110	0	0	10	3	0	5	0	1	0	33	0	0	4	1	305

Data of 2011 year do not include Industrial accidents caused by Great East Japan Earthquake in 2011.

Data sources: https://anzeninfo.mhlw.go.jp/anzen_pg/SIB_FND.aspx (MHLW, Japan)

Return to <https://www.jisha.or.jp/english/statistics/2020efretcs.html>

