

415	crossbeam, principal rafter																							0
416	working platform, boot board																							0
417	passage																							0
418	building, establishment	1			1																			2
419	other temporary buildings, establishments																							0
511	explosive substance																							0
512	inflammable substance																							0
513	inflammable gas																							0
514	harmful substance																							0
515	radiation																							0
519	other hazards, harmful substances																							0
521	metal material																							0
522	lumber, bamboo																							0
523	stone, sand, substance																							0
529	other materials																							0
611	load																							0
612	machine/equipment as load																							0
711	natural ground, rock																							0
712	standing tree																							0
713	water																							0
714	abnormal environment																							0
715	high/cold temperature environment																							0
719	other environments																							0
911	other causal agent																					1	1	2
921	no causal agent																					11		11
999	unclassifiable																						1	1
000	total	1	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	7	1	0		12	2	24

Data of 2011 year do not include Industrial accidents caused by Great East Japan Earthquake in 2011.

Data sources: https://anzeninfo.mhlw.go.jp/anzen_pg/SIB_FND.aspx (MHLW, Japan)

Return to <https://www.jisha.or.jp/english/statistics/2020efretcs.html>

