

415	crossbeam, principal rafter																					0
416	working platform, boot board	1	1																			2
417	passage																					0
418	building, establishment	1				2																3
419	other temporary buildings, establishments				1																	1
511	explosive substance																					0
512	inflammable substance																					0
513	inflammable gas													1								1
514	harmful substance																					0
515	radiation																					0
519	other hazards, harmful substances																					0
521	metal material					1																1
522	lumber, bamboo						1															1
523	stone, sand, substance	2			1	2																5
529	other materials																					0
611	load																					0
612	machine/equipment as load																					0
711	natural ground, rock					6																6
712	standing tree																					0
713	water									4												4
714	abnormal environment																					0
715	high/cold temperature environment										1											1
719	other environments																					0
911	other causal agent																					0
921	no causal agent																					0
999	unclassifiable																					0
000	total	22	1	0	2	11	4	18	0	0	7	1	0	0	1	0	0	5	0	0	0	72

Data of 2011 year do not include Industrial accidents caused by Great East Japan Earthquake in 2011.

Data sources: https://anzeninfo.mhlw.go.jp/anzen_pg/SIB_FND.aspx (MHLW, Japan)

Return to <https://www.jisha.or.jp/english/statistics/2020efretcs.html>

