

415	crossbeam, principal rafter																					0	
416	working platform, boot board																					0	
417	passage	1																				1	
418	building, establishment																			1		1	
419	other temporary buildings, establishments																					0	
511	explosive substance																					0	
512	inflammable substance																					0	
513	inflammable gas																					0	
514	harmful substance																					0	
515	radiation																					0	
519	other hazards, harmful substances																					0	
521	metal material																					0	
522	lumber, bamboo																					0	
523	stone, sand, substance																					0	
529	other materials																					0	
611	load																					0	
612	machine/equipment as load																					0	
711	natural ground, rock	1			4																	5	
712	standing tree				1	1																2	
713	water																					0	
714	abnormal environment																					0	
715	high/cold temperature environment																					0	
719	other environments																					0	
911	other causal agent																					0	
921	no causal agent																			1		1	
999	unclassifiable																					0	
000	total	5	3	0	1	5	2	2	0	0	0	0	0	0	0	0	0	2	0	0	2	0	22

Data of 2011 year do not include Industrial accidents caused by Great East Japan Earthquake in 2011.

Data sources: https://anzeninfo.mhlw.go.jp/anzen_pg/SIB_FND.aspx (MHLW, Japan)

Return to <https://www.jisha.or.jp/english/statistics/2020efretcs.html>

