

415	crossbeam, principal rafter																							0
416	working platform, boot board	1																						1
417	passage																							0
418	building, establishment	1								2														3
419	other temporary buildings, establishments																							0
511	explosive substance																							0
512	inflammable substance																							0
513	inflammable gas																							0
514	harmful substance																							0
515	radiation																							0
519	other hazards, harmful substances																							0
521	metal material					1																		1
522	lumber, bamboo																							0
523	stone, sand, substance																							0
529	other materials																							0
611	load																							0
612	machine/equipment as load																							0
711	natural ground, rock				2	1																		3
712	standing tree																							0
713	water									1														1
714	abnormal environment																							0
715	high/cold temperature environment																							0
719	other environments																							0
911	other causal agent																							0
921	no causal agent																							0
999	unclassifiable																							0
000	total	12	0	0	3	2	1	2	0	0	3	0	0	0	0	0	0	0	0	0	0	0	0	23

Data of 2011 year do not include Industrial accidents caused by Great East Japan Earthquake in 2011.

Data sources: https://anzeninfo.mhlw.go.jp/anzen_pg/SIB_FND.aspx (MHLW, Japan)

Return to <https://www.jisha.or.jp/english/statistics/2020efretcs.html>

