

415	crossbeam, principal rafter	25				1																26	
416	working platform, boot board	5																				5	
417	passage	3	2																			5	
418	building, establishment	27				3			1	2					1							34	
419	other temporary buildings, establishments	2			2																	4	
511	explosive substance																					0	
512	inflammable substance																					0	
513	inflammable gas													2								2	
514	harmful substance											4										4	
515	radiation																					0	
519	other hazards, harmful substances														1							1	
521	metal material	1			6	1	1															9	
522	lumber, bamboo																					0	
523	stone, sand, substance																					0	
529	other materials				1	1														1		3	
611	load	1			1	1	4															7	
612	machine/equipment as load	3			3	11	1	2														20	
711	natural ground, rock	2				2																4	
712	standing tree																					0	
713	water									3												3	
714	abnormal environment											1										1	
715	high/cold temperature environment											4										4	
719	other environments																					0	
911	other causal agent														1						1	2	
921	no causal agent									1											4	5	
999	unclassifiable	1													1						1	3	
000	total	151	3	2	43	29	17	43	1	1	9	9	9	11	6	8	10	30	2	0	8	1	393

Data of 2011 year do not include Industrial accidents caused by Great East Japan Earthquake in 2011.

Data sources: https://anzeninfo.mhlw.go.jp/anzen_pg/SIB_FND.aspx (MHLW, Japan)

Return to <https://www.jisha.or.jp/english/statistics/2020efretcs.html>

