







415	crossbeam, principal rafter	2																				2		
416	working platform, boot board																					0		
417	passage																					0		
418	building, establishment																					0		
419	other temporary buildings, establishments									1												1		
511	explosive substance																					0		
512	inflammable substance																					0		
513	inflammable gas																					0		
514	harmful substance																					0		
515	radiation																					0		
519	other hazards, harmful substances																					0		
521	metal material																					0		
522	lumber, bamboo																					0		
523	stone, sand, substance																					0		
529	other materials																					0		
611	load			2		1																3		
612	machine/equipment as load																					0		
711	natural ground, rock																					0		
712	standing tree																					0		
713	water																					0		
714	abnormal environment																					0		
715	high/cold temperature environment									1												1		
719	other environments																					0		
911	other causal agent																					0		
921	no causal agent																				1	1		
999	unclassifiable																					0		
000	total	4	0	1	2	1	3	5	0	0	2	1	0	0	0	0	0	0	1	0	0	1	0	21

Data of 2011 year do not include Industrial accidents caused by Great East Japan Earthquake in 2011.

Data sources: [https://anzeninfo.mhlw.go.jp/anzen\\_pg/SIB\\_FND.aspx](https://anzeninfo.mhlw.go.jp/anzen_pg/SIB_FND.aspx) (MHLW, Japan)

Return to <https://www.jisha.or.jp/english/statistics/2020efretcs.html>

