







415	crossbeam, principal rafter																						0	
416	working platform, boot board		1																				1	
417	passage									1													1	
418	building, establishment	1	1																				2	
419	other temporary buildings, establishments																						0	
511	explosive substance																						0	
512	inflammable substance																						0	
513	inflammable gas																						0	
514	harmful substance																						0	
515	radiation																						0	
519	other hazards, harmful substances																						0	
521	metal material																						0	
522	lumber, bamboo																						0	
523	stone, sand, substance																						0	
529	other materials																						0	
611	load	1			1																		2	
612	machine/equipment as load																						0	
711	natural ground, rock					1																	1	
712	standing tree																						0	
713	water									1													1	
714	abnormal environment																						0	
715	high/cold temperature environment																						0	
719	other environments																						0	
911	other causal agent																					7	7	
921	no causal agent																3					4	7	
999	unclassifiable																						0	
000	total	6	3	0	1	1	3	1	0	0	2	1	0	0	0	0	3	37	1	0		12	0	71

Data of 2011 year do not include Industrial accidents caused by Great East Japan Earthquake in 2011.

Data sources: [https://anzeninfo.mhlw.go.jp/anzen\\_pg/SIB\\_FND.aspx](https://anzeninfo.mhlw.go.jp/anzen_pg/SIB_FND.aspx) (MHLW, Japan)

Return to <https://www.jisha.or.jp/english/statistics/2020efretcs.html>

