

362	搬機	1	73	20	15	9	26	33	1								2		6			186
363	人力機械					1		1														2
364	手工具				1				56										4	2		63
371	はしご等	86	11	9		2		1	2										8			119
372	玉掛用具																					
379	その他の用具	8	39	8	24	6	9	14	9			21							17	1		156
391	その他の装置、設備	5	20	8	9	1	5	19	6			30							5	1		109
411	足場		1																			1
412	支保工	1																				1
413	階段、 栈橋	106	41	6															16			169
414	開口部	4	3	1																		8
415	屋根、 はり、 もや、 けた、 合掌	2																				2
416	作業 床、歩 み板	14	146	3				1											5			169

	利																					
529	その他の材料		7	1	8	1		1	5			17	1							12		53
611	荷姿の物	6	19	12	16	9	7	14	6			2								67		158
612	機械装置	1	1		2	2		2					1							2		11
711	地山、岩石	1																				1
712	立木等																					
713	水		4									3										7
714	異常環境等		1										2									3
715	高温・低温環境		1		1							24										26
719	その他の環境等		23	1	1							4								2		31
911	その他の起因物		5	1	1			2	1	4		9								9		32
921	起因物なし	1	26	2					1											98	1	129
999	分類不能		2						1			1										4
	計	315	946	145	122	44	75	1,078	346	1		172	15	3	2			40	1	280	8	3,593

事例数に2011年の東日本大震災の災害事例は含まれていない。死傷災害全数の約1/4の抽出事例数である。

出典：https://anzeninfo.mhlw.go.jp/anzen_pgm/SHISYO_FND.aspx(職場のあんぜんサイト)

Return to https://www.jisha.or.jp/international/topics/202207_04.html